ACHTUNG! ATTENTION! ATTENTION! OPGELET! OBS! OBS!

Typ Type Type Type Type Typ	**SECUMAR Golf Twin 275**
Ersatz-Packung **Spare-Kit** **Kit de rechange** **Reserveset** **Reservesæt** **Reservförpackning**	**60 g CO_2** **Art. Nr. 11896** obere Kammer/ upper chamber/ bovenkamer/ øvre kammer **60 g CO_2** **Art. Nr. 11897** untere Kammer/ lower chamber/ onderkamer/ nedre kammer
Verschluß **Buckle** **Boucle** **Sluiting** **Spænde** **Bältesticklås**	
Packen **Packing** **Emballage** **Invouwen** **Pakke instruktion** **Ihoppackning**	
SECUMAR SERVICE	**1** Jahr/ Year/ Année/ Jaar/År/ År → **1** Jahr/ Year/ Année/ Jaar/ År/ År → letzter/ last/ dernier/ laatste/ sidste/ siste **Service** **10 Jahre/ Years/ Années/ Jaar/ År/ År**

SECUMAR
BERNHARDT APPARATEBAU GMBH U. CO.
BREDHORNWEG 39 • 25488 HOLM
GERMANY

TN 14131 /08.10-SBI

Produkt-Info - Product Information - Produktinformatie - Produktinformation - Produktinformationen -

BERNHARDT APPARATEBAU GmbH u. Co.
RETTUNGSGERÄTE FÜR SCHIFFFAHRT UND LUFTFAHRT
SECUMAR®

Bredhornweg 39
D-25488 Holm
Tel: +49-4103-1250
Fax: +49-4103-125100

EC DECLARATION OF CONFORMITY

We hereby declare that the follofing specified equipment complies with the Marine Equipment Directive 96/98/EC, as amanded, last amanded by Directive 2008/67/EC.

Lifejacket SECUMAR Golf 275 Twin SOLAS

Manufatured by:
BERNHARDT APPARATEBAU GmbH u. Co.
Bredhornweg 39, 25488 Holm/Germany

This equipment has been testet to verify compliance with the following Regulations and Testing Standards:

- SOLAS 74/78, amanded by Reg. III/7, III/225, III/34
- IMO Res. MSC.81(70), amanded by MSC.200(80) and MSC.207(81)
- IMO Res. MSC.36(63) and Res. MSC.97(73) [HSC Code]
- IMO Res. MSC.48(66) [LSA Code]

Type-Examination (Module B) Certificate No. 94704-10HH issued by Germanischer Lloyd.
Surveillance certificate No. 94705-10HH (Module D) issued by Germanischer Lloyd.

Product affixed with following mark and identification:

0801
10

A Technical Construction File for this equipment is retained at the following address:
BERNHARDT APPARATEBAU GmbH u. Co.
Bredhornweg 39, 25488 Holm/Germany

Jan-Ulrich Bernhardt
Managing Director
Holm, November 17th 2010

ACHTUNG! ATTENTION! ATTENTION! OPGELET! OBS! OBS!

Typ Type Type Type Type Typ	**SECUMAR Golf Twin 275**
Ersatz-Packung **Spare-Kit** **Kit de rechange** **Reserveset** **Reservesæt** **Reservförpackning**	60 g CO_2 **Art. Nr. 11896** obere Kammer/ upper chamber/ bovenkamer/ øvre kammer 60 g CO_2 **Art. Nr. 11897** untere Kammer/ lower chamber/ onderkamer/ nedre kammer
Verschluß **Buckle** **Boucle** **Sluiting** **Spænde** **Bältesticklås**	
Packen **Packing** **Emballage** **Invouwen** **Pakke instruktion** **Ihoppackning**	
SECUMAR SERVICE	**1** Jahr/ Year/ Année/ Jaar/ År/ År → **1** Jahr/ Year/ Année/ Jaar/ År/ År → letzter/ last/ dernier/ laatste/ sidste/ siste **Service** 12 SN300 FSR → 13 SN300 FSR → 14 SN300 FSR ..... ~~23 SN300 FSR~~ 10 Jahre/ Years/ Années/ Jaar/ År/ År

TN 14131 /08.10-SBI

SECUMAR
BERNHARDT APPARATEBAU GMBH U. CO.
BREDHORNWEG 39 • 25488 HOLM
GERMANY

Produkt-Info - Product Information - Produktinformatie - Produktinformation - Produktinformationen -

BERNHARDT APPARATEBAU GmbH u. Co.
RETTUNGSGERÄTE FÜR SCHIFFFAHRT UND LUFTFAHRT
SECUMAR®

Bredhornweg 39
D-25488 Holm
Tel: +49-4103-1250
Fax: +49-4103-125100

EC DECLARATION OF CONFORMITY

We hereby declare that the follofing specified equipment complies with the Marine Equipment Directive 96/98/EC, as amanded, last amanded by Directive 2008/67/EC.

Lifejacket SECUMAR Golf 275 Twin SOLAS

Manufatured by:
BERNHARDT APPARATEBAU GmbH u. Co.
Bredhornweg 39, 25488 Holm/Germany

This equipment has been testet to verify compliance with the following Regulations and Testing Standards:

- SOLAS 74/78, amanded by Reg. III/7, III/225, III/34
- IMO Res. MSC.81(70), amanded by MSC.200(80) and MSC.207(81)
- IMO Res. MSC.36(63) and Res. MSC.97(73) [HSC Code]
- IMO Res. MSC.48(66) [LSA Code]

Type-Examination (Module B) Certificate No. 94704-10HH issued by Germanischer Lloyd.
Surveillance certificate No. 94705-10HH (Module D) issued by Germanischer Lloyd.

Product affixed with following mark and identification:

0801
10

A Technical Construction File for this equipment is retained at the following address:
BERNHARDT APPARATEBAU GmbH u. Co.
Bredhornweg 39, 25488 Holm/Germany

Jan-Ulrich Bernhardt
Managing Director
Holm, November 17th 2010