







ACHTUNG! ATTENTION! ATTENTION! OPGELET! OBS! OBS!



Bredhornweg 39 Tel: +49-4103-1250
D-25488 Holm Fax: +49-4103-125100

<p>Typ Type Type Type Type Typ</p>	<p>SECUMAR Golf Twin 275 Harness</p> 	
<p>Ersatz-Packung Spare-Kit Kit de recharge Reserveset Reservesæt Reservförpackning</p>	<p>60 g CO₂ Art. Nr. 11896</p> <p>obere Kammer/ upper chamber/ bovenkamer/ øvre kammer</p>	
	<p>60 g CO₂ Art. Nr. 11897</p> <p>untere Kammer/ lower chamber/ onderkamer/ nedre kammer</p>	
<p>Verschuß Buckle Boucle Sluiting Spænde Bältesticklås</p>		
<p>Packen Packing Emballage Invouwen Pakke instruksjon Ihoppackning</p>		
<p>SECUMAR SERVICE</p>	<p>1 Jahr/ Year/ Année/ Jaar/ År/ Ar 1 Jahr/ Year/ Année/ Jaar/ År/ Ar letzter/ last/ dernier/ laatste/ sidste/ siste Service</p>  <p>← 10 Jahre/ Years/ Années/ Jaar/ År/ Ar →</p>	

SECUMAR
BERNHARDT APPARATEBAU GMBH U. CO.
BREDHORNWEG 39 • 25488 HOLM
GERMANY

Produkt-Info - Product Information - Produktinformatie - Produktinformation - Produktinformationen -

EC DECLARATION OF CONFORMITY

We hereby declare that the following specified equipment complies with the Marine Equipment Directive 96/98/EC, as amended, last amended by Directive 2014/93/EU.

Lifejacket SECUMAR Golf 275 Twin

Manufactured by:
BERNHARDT APPARATEBAU GmbH u. Co.
Bredhornweg 39, 25488 Holm/Germany

This equipment has been tested to verify compliance with the following Regulations and Testing Standards:

- SOLAS 74/78 as amended Reg. III/5, III/7, III/22, III/34, X/3
- LSA Code I, II incl. MSC.207(81)
- HSC Code Reg. 8

The compliance with above mentioned resolutions and directives has been confirmed by DNV GL SE (Notified Body No.: 0098; Address: Brooktorkai 18, 20457 Hamburg/Germany) with EC Certificate Type Examination No. 94704-40 HH (Module B) and EC Certificate of Conformity Quality System No. 94705-10 HH (Module D).

The devices are marked with



A Technical Construction File for this equipment is retained at the following address:
BERNHARDT APPARATEBAU GmbH u. Co.
Bredhornweg 39, 25488 Holm/Germany







Benjamin Bernhardt
Managing Director
Holm, 29/03/2016

TN 14129 /03.16-SBI

ACHTUNG! ATTENTION! ATTENTION! OPGELET! OBS! OBS!

TN 14129 /03.16-SBI

<p>Type Type Type</p>	<p>Ersatz-Packung Spare-Kit Kit de rechange Reservesæt Reservset Reservförpackning</p>	<p>Verschluss Buckle Boucle Sluiting Spånde Bältesticklås</p>		<p>Packen Packaging Emballage Invouwen Pakke instruksjon Inoppackning</p>		<p>SECUMAR SERVICE</p>  <p>10 Jahre/ Years/ Années/ Jaar/ Ar/ Ar 1 Jahr/ Year/ Année/ letzter/ last/ dernier/ laatste/ sidste/ siste Service</p>
<p>SECUMAR Golf Twin 275 Harness ISO 12402-2 275</p>	<p>60 g CO₂ Art. Nr. 11896 60 g CO₂ Art. Nr. 11897</p>  <p>obere Kammer/ upper chamber/ bovenkamer/ øvre kammer untere Kammer/ lower chamber/ onderkamer/ nedre kammer</p>					

SECUMAR
BERNHARDT APPARATEBAU GMBH U. CO.
BREDDHORNWEG 39 • 25488 HOLM
GERMANY

Produkt-Info - Product Information - Produktinformative - Produktinformation - Produktinformationen

EC DECLARATION OF CONFORMITY

We hereby declare that the following specified equipment complies with the Marine Equipment Directive 96/98/EC, as amended, last amended by Directive 2014/93/EU.

Lifejacket SECUMAR Golf 275 Twin

Manufactured by:

BERNHARDT APPARATEBAU GmbH u. Co.
Breddhornweg 39, 25488 Holm/Germany

This equipment has been tested to verify compliance with the following Regulations and Testing Standards:

- SOLAS 74/78 as amended Reg. III/5, III/7, III/12, III/34, X/3
- LSA Code I, II incl. MSC.207(81)
- HSC Code Reg. 8

The compliance with above mentioned resolutions and directives has been confirmed by DNV GL SE (Notified Body No.: 0098; Address: Brooktorkei 18, 20457 Hamburg/Germany) with EC Certificate Type Examination No. 94704-40 HH (Module B) and EC Certificate of Conformity Quality System No. 94705-10 HH (Module D).

The devices are marked with



A Technical Construction File for this equipment is retained at the following address:
BERNHARDT APPARATEBAU GmbH u. Co.
Breddhornweg 39, 25488 Holm/Germany

Benjamin Bernhardt
Managing Director
Holm, 29/03/2016

BERNHARDT
APPARATEBAU
GmbH u. Co.
RÜTTUNGSGERÄTE
FÜR SCHIFFFAHRT
UND LUFTFAHRT
SECUMAR
Tel: +49-4103-1250
Breddhornweg 39
D-25488 Holm
Fax: +49-4103-125100