













ACHTUNG! ATTENTION! ATTENTION! OPGELET! OBS! OBS!

Typ Type Type Type Type	SECUMAR Bolero 150 
Ersatz-Packung Spare-Kit Kit de rechange Reserveset Reservesæt Reservförpackning	Art-Nr. 11433  
Verschluß Buckle Boucle Sluiting Spænde Bältsticklås	
Packen Packing Emballage Invouwen Pakke instruktio Ihoppackning	
SECUMAR SERVICE	2 Jahre/ Years/ Années/ Jaar/ År/ År 2 Jahre/ Years/ Années/ Jaar/ År/ År letzter/ last/ dernier/ laatste/ sidste/ siste Service 

SECUMAR
BERNHARDT APPARATEBAU GMBH U. CO.
Bredhornweg 39 25488 Holm
GERMANY

ACHTUNG! ATTENTION! ATTENTION! OPGELET! OBS! OBS!

Typ Type Type Type Type	SECUMAR Bolero 150 
Ersatz-Packung Spare-Kit Kit de rechange Reserveset Reservesæt Reservförpackning	Art-Nr. 11433  
Verschluß Buckle Boucle Sluiting Spænde Bältsticklås	
Packen Packing Emballage Invouwen Pakke instruktio Ihoppackning	
SECUMAR SERVICE	2 Jahre/ Years/ Années/ Jaar/ År/ År 2 Jahre/ Years/ Années/ Jaar/ År/ År letzter/ last/ dernier/ laatste/ sidste/ siste Service 

SECUMAR
BERNHARDT APPARATEBAU GMBH U. CO.
Bredhornweg 39 25488 Holm
GERMANY

TN 13029/SBI-06.10

TN 13029/SBI-06.10

Produkt-Info - Product Information - Product Information - Produktinformatie - Produktinformation - Produktinformationen -

Produkt-Info - Product Information - Product Information - Produktinformatie - Produktinformation - Produktinformationen -